

TestkingIT

Testking IT

> Contact Us

Login / Register

Search...



HOME

ALL VENDORS

★ GUARANTEE

? FAQ

TESTIMONIALS

CART (0)



Try **Desktop Test Engine** before you buy

We're not the only ones **happy** about TestKingsIT Practice Material ...

48236+ customers in 100+ countries use TestKingsIT Test Engine. Meet our customers.



<http://www.testkingit.com/>

Latest practice material - Exam Cram - TestKingIT

Exam : HP0-645

Title : Implementing HP ProLiant Servers

Vendors : HP

Version : DEMO

NO.1 Which agent-layer components facilitate system software updates and version management on HP

ProLiant servers? Select TWO.

- A. Version Control Repository Manager (VCRM)
- B. ActiveUpdate
- C. Software Version Control Manager (SVCM)
- D. Version Control Agents (VCAs)
- E. Insight Manager 7
- F. Version Revision Manager (VRM)

Answer: AD

NO.2 When memory is the only component to be tested, which diagnostic option should be selected?

- A. QuickCheck
- B. Automatic
- C. Prompted
- D. CPQSET+

Answer: C

NO.3 What is the recommended average disk queue length for a single disk spindle?

- A. Less than one
- B. Less than two
- C. Less than four
- D. Less than eight
- E. Less than sixteen

Answer: B

NO.4 How do the HP Enterprise Configurator solution sizers gain knowledge of your application environment?

- A. They place all HP ProLiant servers in three categories: small, medium, and large. Based on your selection, they then determine the type of server platform you need.
- B. They use an interview process to determine the workload requirements for your application server.
- C. They use information collected by the Survey Utility.
- D. They use your personal profile created in Enterprise Configurator to recommend server platforms.

Answer: B

NO.5 Which security feature of Insight Manager 7 is used to encrypt all communication between the browser and management server?

- A. authentication
- B. Secure Sockets Layer (SSL)
- C. digital certificate
- D. transitive trust

Answer: B

NO.6 What is the most likely problem when you receive only audible codes (beeps) during POST?

- A. The monitor signal cable is not connected.
- B. The system sees intermittent memory parity errors.
- C. No memory modules are present.
- D. The monitor is in power saver mode.

Answer: C

NO.7 During configuration of the ProLiant Support Pack deployed by the Remote Deployment Utility to a server, you are asked to set the Device Authentication relationship. Which relationship is the most secure?

- A. Trust All
- B. Trust by Name
- C. Trust by Certificate
- D. Trust Administrator

Answer: C

NO.8 A hard drive appears to be failing in an HP ProLiant server. Which HP software support tool can be used to diagnose potential hard drive errors?

- A. Server Diagnostics
- B. System Erase Utility
- C. System Configuration Utility
- D. Inspect Utility

Answer: A

NO.9 You want to upgrade an existing HP ProLiant ML370 G2 server with an additional processor. The server is running a business-critical application and requires maximum uptime. How should you identify the correct part number for the new processor?

- A. Restart the server and identify the processor type and speed during POST.
- B. Use the server serial number to decipher the processor type and speed.
- C. Open the server and look at the model and speed markings on the processor.
- D. Open the server and read this information on the inside cover.
- E. Non applicable, the HP ProLiant ML370 G2 server does not support multiple processors.

Answer: B

NO.10 You need to initiate a cold reset and bring the host server back online after the operating system has become unresponsive. Which feature of HP Remote Insight Lights-Out Edition (RILOE) enables you to perform this task?

- A. remote reset
- B. graphical remote console
- C. server failure alerting
- D. reset and failure sequence replay

Answer: A

NO.11 What is the shortest Survey report you can run that would display an option removed from the system?

- A. Show only differences
- B. Show all details and differences
- C. Show only major differences
- D. Show standard details and differences

Answer: C

NO.12 Although you upgraded an application to improve server performance, you noticed that server performance was actually degraded. You were then informed that a user admitted opening an email attachment that might have contained a virus. What steps should you take to address this

problem?

Select TWO.

- A. View Insight Manager 7 to determine the device status.
- B. Update to the latest virus definition.
- C. Downgrade the application.
- D. Compare the application requirements to the server configuration.
- E. Run virus scanning software and restart the server to remove any memory-resident virus remnants.

Answer: BE

NO.13 After a field engineer adds a second array controller to an HP ProLiant server, the operating system will not boot. What is the likely cause of this problem?

- A. interrupt conflicts
- B. incorrect slot order
- C. controller boot order
- D. incorrect jumper settings

Answer: C

NO.14 You are using NetIQ to resolve alerts in your enterprise. Where can you find the Management Information Base (MIB) for ProLiant servers?

- A. OnSite Agents Reference Set
- B. MIB directory on the SmartStart CD
- C. ProLiant Essentials ?NetIQ Integration Pack
- D. Compaq directory of the NetIQ distribution CD
- E. Management Toolkit Directory on the Management CD

Answer: E

NO.15 What is the act of mirroring across two physical controllers known as?

- A. mirroring
- B. striping
- C. duplexing
- D. parity

Answer: C

NO.16 What is meant by the term "Scope of work"?

- A. a detailed list of project deliverables

- B. a detailed summary of work completed
- C. a brief background of a project or component
- D. a general objective for a customer engagement

Answer: A

NO.17 You are monitoring an HP ProLiant ML530 server. The server is configured with a Remote Insight Lights-Out Edition (RiLOE) board from a management PC in the same network. What is the recommended video resolution on the remote server compared to the video setting of the management PC?

- A. The resolution of the remote server should be lower than the management PC.
- B. The resolution of the remote server should be higher than the management PC.
- C. The resolution of the remote server should be lower than or equal to the management PC.
- D. Nothing, the resolution does not make a difference.

Answer: C

NO.18 You have four HP hot-pluggable drives in a RAID 1+0 configuration. On the second drive, only the amber LED is illuminated. What is the recommended action?

- A. Replace the second drive.
- B. The array is lost; you cannot do anything to recover it.
- C. Wait until the first LED (nline? illuminates; then replace the failed drive.
- D. Replace the second drive and manually start rebuilding the array in the ACU.

Answer: A

NO.19 You are configuring an HP ProLiant server with multiple storage devices using a Wide SCSI controller.

Excluding the controller, how many SCSI IDs are available on a Wide SCSI bus?

- A. 7
- B. 8
- C. 15
- D. 16

Answer: C

NO.20 You need to invoke Advanced Mode Diagnostics in order to run loopback tests on an HP ProLiant server. Which step is required to invoke Advanced Mode Diagnostics?

- A. Press the Ctrl+Alt+Delete key sequence at the main menu.
- B. Press the Ctrl+A key sequence at the System Utilities screen.
- C. Select Test Computer at the Diagnostics and Utilities menu.
- D. Press the F9 key to load Advanced Mode using ROM-based diagnostics.

Answer: B